

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES




Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**







Fig 4

TORQUE

Master




Leverage Enhancing
Screwdriver

**NO MORE
LOOSE
SCREWS!**



PATENT PENDING





STAMP STEEL

driver		
0.75	4/2/2002	
SCALE	DATE	




Fig 7a




Fig 7





TORQUE
Master
Leverage Enhancing
Screwdriver

**NO MORE
LOOSE
SCREWS!**



Fig 7B






Fig 9